

A320 PILOT TABLE ASSEMBLY REPAIR SOLUTION





Our services range from simple seat repairs to full provision for seats, carpets, plastic parts, composite parts, mechanical parts, sidewalls, galleys, curtains, and PSU on both a planned and unscheduled maintenance basis.

We currently hold approvals

- CAA Part 145

- FAR Part 145
- ► TCCA CAR 573

- CAA Part21G
- ► EASA Part 145

A320 Pilot Table Assembly Part Number

D2511225800000

D2511411800000

D2511018000100

D2511113100400

D2511113100500

D2511113200100

D2511113100100

D2511168500000

F2511211600000

F2511223200000

F2511223200200


A320 Pilot Table Lower Assembly Plastic Table Part Number

D2511148900000

Before



After



Cabinair Services Ltd ©2023





About us



Cabinair Services offers many specialised solution for aircraft interiors, one of our specialities is the refurbishment of sidewall panels, including their re-lamination. With EASA Part 145, FAR Part 145 and TCCA CAR 573, this requirement will be well within the capability of our technicians and the company's approval to release with the required certification

Contact



Aerospace Interiors Centre, Blackhorse Road, Letchworth, Herts, SG6 1HB, UK

+44 (0) 1462 650070

sales@cab.aero

cabinairservices.com

Cabinair Services Ltd ©2023